

TYPE "B" TYPICAL CONCRETE JOINT REPAIR

REV. 8/1999

300–9